

Case Boring




Precision Case Boring Service.

- V-Twin Motor Shop will use a vertical mill to enlarge the cylinder hole or head chamber to accept Big Bore Spigot barrels.
- Ship cases to V-Twin with a turn around time of 15 days.

VT No.	Type
60-0165	Case
60-0171	Heads

Generator Rebuilding Service



Motor Shop Services. We now offer generator rebuilding service for original H-D generators. Send us your old, tired, worn out generator and we will completely rebuild with new field coils, armature, brushes, seals, gear and corresponding regulator. All units are tested for correct output. Specify regulator type desires.

- | VT No. | Item |
|---------|---|
| 60-0200 | 12 Volt 2 Brush for 1965-up Generator |
| 60-0202 | 6 Volt 2 Brush for 1958-64 Generator |
| 60-0203 | 6 Volt 3 Brush for 1930-57 Generator |
| 60-0204 | Convert 3 Brush 6 Volt to 2 Brush 12 Volt |
| 60-0205 | 6 Volt 2 Brush for Cooled Generator 1958-64 |



Brake Drum Sprocket Replacement Service for 1930-72 Big Twins, 1952-78 Sportster and 1935-52 45" Solo models. Send in your old brake drum and we will install new sprocket, splash or dust ring correctly with hot riveting as original. All drums inspected for suitability and customer notified if not serviceable. Work order number required before sending in. Contact Motor Shop Service Department prior to shipping your drum in.

VT No. 60-0259




VT No. Carb 60-0195 M88, M51L, M41, M51 and M74

60-0345 M88, M51L, M41, M51 and M74

Linkert Rebuild Service. Parts billed separately as required.

Alternator Sealing Ring Service



Motor Shop Alternator Sealing Ring Replacement Service. Ship in 1970-up left hand case with damaged O-Ring lip and we will machine out and replace with new steel sealing ring.

VT No. 60-0164



Big Twin Alternator Rotor Puller uses the two threaded holes in rotor to allow removal of rotor.

VT No. 16-0693



Big Twin Alternator Rotor Puller uses the sprocket shaft end to center and the two threaded holes in rotor to allow removal of rotor.

VT No. 16-1054



Alternator Repair Ring Only.
VT No. 16-0692