



33-0172

### 4 1/2" Chrome Bullet Style Spotlamp Trim

- Held in place by existing headlamp bulb and rim.

VT No. 33-0172



33-0551



33-1198



33-1198  
Installed



33-0546 Installed



33-0811  
Installed

### Spotlamp Trim Ring Set

- Allow installation of visors on 1987-up models, sold as pair.

VT No.	Item
33-0551	Ring Set
33-1198	Billet Trim Ring Set
42-0202	Visors, pair



33-0811

### Spotlamp Dress Ring

- Features a recessed "frenched" deep design. Also available with built in visor.

VT No.	Type
33-0546	Frenched
33-0811	Frenched with visor

