



Linkert



49-0631



49-0631



49-0633




49-0633

**Got a Bare Brass Linkert Body
We Can Rebuild It!**



Watch Our Video!
[http://www.youtube.com/
user/TeddCycle](http://www.youtube.com/user/TeddCycle)



Linkert
M74

VT No.
60-0188

VT No.
60-0148



Linkert Rebuild Service. Parts
billed separately as required.



Linkert Hand Tool Tap, sold each.

Thread	VT No.
10-32	16-1400
12-24	16-1401
1/4 x 40	16-1402
5/16 x 18	16-1403
5/16 x 32	16-1404
Kit	16-1405



49-0635



49-0635



35-0082



49-0398



49-0635

Replica Linkert Carburetor is completely assembled with all
internals with brass body. *Note: Without throttle arm.

VT No.	Model	Type	Year
49-0631	M88	45 SV	1941-52
49-0266*	M88	45 SV	1941-52
49-0633	M51L	Big Twin SV	1937-48
49-0398*	M51L	Side Valve	1936-48
35-0082	M74	Big Twin	1948-65
49-0635	M51	Big Twin SV	1937-48
35-1350	Bonn	Indian Chief	1935-53
48-0926	Can		



49-0635 Installed on Knucklehead Motor



29-1115
Installed